

BUILDING SAFETY CERTIFICATE

Ref. No. : 1583

Dated: 15.05.24

It is Certified that the Existing Building of Surendranath Centenary School at H.B. Road, Dipatoli, Ranchi-834001 is having Block's/Floor's as per details below:

Details of Block (S)	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor (S) In the Block	4	3	-	-	-	-

The Building is occupied by Surendranath Centenary School have complied with the Building safety requirement in accordance with National Building Code Rules, and verified by the officers concerned of building construction department on 15.05.2024 in the Presence of Administrative /Manager of Surendranath Centenary School, H.B. Road, Dipatoli, Ranchi and that the building/premises is fit for occupancy for running school with from 15.05.2024 for period of one year in accordance with rule and subject to compliance of the specific conditions as appended.

Kumari
15/05/24
(KRISHNA MURARI)
JUNIOR ENGINEER
MEDICAL SECTION NO 1
RIMS RANCHI

भवन निर्माण विभाग
चिकित्सा प्रशाखा सं०-०१
रिम्स, बरियातु, राँची

Ganesh Kumar
15.05.24
(GANESH KUMAR)
ASSITANT ENGINEER
MEDICAL SUB DIVISION NO 1
RMCH, BARIATU, RANCHI

अवर प्रमण्डल पदाधिकारी
भवन निर्माण विभाग
चि०अ० प्रमण्डल सं-१, बरियातु

Deepak Kumar Mahato
(DEEPAK KUMAR MAHTO)
EXECUTIVE ENGINEER
BUILDING CONSTRUCTION DEPARTMENT
BUILDING DIVISION NO 2 RANCHI

ATTESTED

Sanita Senha

Principal

Surendranath Centenary School
Dipatoli, Ranchi-834009